

Bios Update VPC17


This document is to provide a guide to updating a BIOS for VPC 17 to resolve the VB-CAM-001 restart issue.

Required equipment:


IFP
VPC
VPC17 zip file

Instructions:

1. Select VPC 17 zip file, right click and select unzip.
2. Open extracted VPC folder.
3. Open the “Windows” folder



4. Right click on the “F” file and Run as administrator. The BIOS will update automatically.



Note: Do not turn off IFP or VPC during the BIOS update as this may cause damage to the units.